

How To Use

Knock Out

Mount the Alpha® Knock Out blade onto the Trac Star 2000 wet saw.

When mounting the blade onto the power tool, make sure the directional rotation of the blade matches the spindle rotation of the power tool.

Set the v-groove track on material to be cut and place the Trac Star wet saw on the v-groove track.

Turn on the spindle to start blade rotation.

Set the traverse speed by adjusting the variable speed motor knob to desired cutting speed. (0 – 6 ft. per min)

Turn on the water supply.

Start the movement of the Trac Star to start the cutting process. This will cut 3cm (1-1/4") thick materials in one-pass.

Review the operation manual of the Trac Star 2000 for proper set-up and operating procedures for this saw. (www.inter-tool.com)