# Alpha® Wet Sanding and Polishing Kit Instruction Manual

*Tool sold separately

Part No: WSPKIT
Version 1

TABLE OF CONTENTS

SERVICE

Use only Alpha Professional Tools® accessories and spare parts. Should components which have been described need to be exchanged, please contact your dealer or Alpha Professional Tools®.

⚠ CAUTION

- Attach the Wet Sanding & Polishing Kit correctly by following the procedure in this instructional manual.
- During operation, be sure to wear personal safety equipment.

NEED MORE INFORMATION

For information on Alpha Professional Tools® complete product line, visit us on the web at www.alpha-tools.com.

ALPHA® WET SANDING & POLISHING KIT OVERVIEW

Positioning Holes

Splash Guard

Plastic Tie

Adapter

Loc-line Assembly

Memory Wrap
(3ft. / 1m)

Water Hose Assembly
(15ft. / 4.5m)

Quick Connect Adapter

GFCI

ATTACHING THE WATER HOSE ASSEMBLY

1. Attach and tighten the Water Hose Assembly onto the Adapter.

Adapter

Loc-line Assembly

Water Hose Assembly

ATTACHING THE WSPKIT TO THE VARIABLE-SPEED GRINDER / SANDER / POLISHER

Small Grinder

Large Grinder

Water Hose Assembly

Side Handle

Splash Guard

Loc-line Assembly

Electric Power Cord

Memory Wrap (3ft. / 1m)

Water Hose Assembly

INSTALLATION OF EASYON-EASYOFF SLEEVE

1. Wrap the EasyOn-EasyOff Sleeve around the Water Hose Assembly and electrical cord.

2. Finish the wrapping procedure until the entire EasyOn-EasyOff Sleeve is secured.

USING THE HOOK & LOOP STRAP(S)

NOTE: Use the Hook & Loop Straps as necessary to attach the hose assembly to the Variable-Speed Grinder/Sander/Polisher.

**NOTE:** Position the straps away from the vent ports of the Variable-Speed Grinder/Sander/Pollisher.

Hook & Loop Strap 1-1/2"(W) x 12"(L)

Small Angle Grinder

Large Angle Grinder

Hook & Loop Strap 1-1/2"(W) x 18"(L)

Hook & Loop Strap 1/2"(W) x 12"(L)

INSTALLATION OF THE GFCI

1. Install the GFCI to the power tools power cord as shown. Connect to Power and check the GFCI for proper function.

TESTING IN-LINE GFCI UNIT

1. Connect GFCI to a single-phase AC power supply
2. Verify that the indicator lens shows red (indicating output voltage).
3. Press the test button to verify that the red in the indicator lens disappears.
4. Press the reset button to verify the red indicator is visible.
5. The GFCI is now ready to use.

RESET BUTTON

TEST BUTTON

- Indicator view lens.
- RED lens indicates power
- CLEAR lens indicates no power

INSTALLATION OF THE QUICK CONNECT ADAPTER

1. Secure the Quick Connect Adapter to the Water Hose Assembly.

ALPHA® WSPKIT SCHEMATIC & PART LISTS

ITEM NO.	PART NO.	DESCRIPTION	QUANTITY
1	133791	Splash Guard	1
2	140004	Loc-Line Assembly	1
3	PDH-CABLETIES	Plastic Tie	2
4	133780	Adapter (1/4 NPT>>>M10*P1.0)	1
5	210129	Water Hose Assembly (15ft./4.5m)	1
6	210124	Memory Wrap (3ft./1m)	1
7	133773	Quick Connect Adapter	1
8	GFCI-1	GFCI Plug (120V)	1
9	133551	Hook & Loop Strap (1/2"x12")	1
10	140003	Hook & Loop Strap (1-1/2"x 12")	1
11	140008	Hook & Loop Strap (1-1/2"x18")	1

Alpha Professional Tools®

103 Bauer Drive, Oakland, NJ 07436 • 800-648-7229 • Fax: 800-286-0114
www.alpha-tools.com