

Helpful Hints

AIR-300 Pneumatic Polisher

- Drain compressed air and water daily from air holding tank at the end of work shift to avoid any problems with rust.
- In-line air dryers are recommended to extend the life of the tool.
- Check compressors and air lines time to time since old or worn compressors, which emit oil through the air lines, can dramatically shorten the life of the tool.
- Do not leave the tool submersed in water. This could expose the inner moving parts to moisture, which will shorten the life of the tool.
- Do not leave threaded accessories (backer pads) on the spindle of tool for extended periods of time; this may result in making it difficult to remove these accessories.
- Excessive force or impact to the spindle may result in premature failure of gears and/or bearings, which may not be immediately evident.