


Alpha[®] Wet Sanding and Polishing Kit Instruction Manual



*Tool sold separately

Part No: WSPKIT Version 12/2020



www.alpha-tools.com

►TABLE OF CONTENTS

Alpha® Wet Sanding & Polishing Kit Overview	3
Attaching The WSPKIT To The Variable-Speed Grinder / Sander / Polisher	4
Attaching The Water Hose Assembly	4
Installation Of Easy On-Easy Off Sleeve	5
Using The Hook & Loop Straps	5
Installation Of The GFCI	6
Testing In-Line GFCI Unit	6
Connecting The Water Supply	7
Alpha® WSPKIT Schematic & Part List	8

SERVICE

Use only Alpha Professional Tools® accessories and spare parts. Should components which have been described need to be exchanged, please contact your dealer or Alpha Professional Tools®.


▲ CAUTION

- Attach the Wet Sanding & Polishing Kit correctly by following the procedure in this instructional manual.
- · During operation, be sure to wear personal safety equipment.


NEED MORE INFORMATION

For information on Alpha Professional Tools® complete product line, visit us on the web at www.alpha-tools.com.

► ALPHA® WET SANDING & POLISHING KIT OVERVIEW




► ATTACHING THE WSPKIT TO THE VARIABLE-SPEED GRINDER / SANDER / POLISHER



► ATTACHING THE WATER HOSE ASSEMBLY


1. Attach and tighten the Water Hose Assembly onto the Adapter.




► NSTALLATION OF EASYON-EASYOFF SLEEVE

- 1. Wrap the EasyOn-EasyOff Sleeve around the Water Hose Assembly and electrical cord.
- 2. Finish the wrapping procedure until the entire EasyOn-EasyOff Sleeve is secured.







► USING THE HOOK & LOOP STRAPS



► INSTALLATION OF THE GFCI


1. Install the GFCI to the power tools power cord as shown. Connect to Power and check the GFCI for proper function.






TESTING IN-LINE GFCI UNIT

- 1. Connect GFCI to a single-phase AC power supply
- 2. Verify that the indicator lens shows red (indicating output voltage).
- 3. Press the test button to verify that the red in the indicator lens disappears.
- 4. Press the reset button to verify the red indicator is visible.
- 5. The GFCI is now ready to use.




► CONNECTING THE WATER SUPPLY


Connect to Water Supply - 1



Connect to Water Supply - 2



► ALPHA[®] WSPKIT SCHEMATIC & PARTS LIST



ITEM NO.	PART NO.	DESCRIPTION	QUANTITY
1	133791	Splash Guard	1
2	140004	Loc-Line Assembly	1
3	PDH-CABLETIES	Plastic Tie	2
4	133780	Adapter (1/4 NPT>>>M10*P1.0)	1
5	210129	Water Hose Assembly (15ft./4.5m)	1
6	210124	Memory Wrap (3ft./1m)	1
7	658-113	Water Quick Coupler w/Shut-off Valve	1
8	GFCI-1	GFCI Plug (120V)	1
9	133551	Hook & Loop Strap (1/2"x12")	1
10	140003	Hook & Loop Strap (1-1/2"x 12")	1
11	140008	Hook & Loop Strap (1-1/2"x18")	1
12	133805	O-Ring	1

🕗 Alpha Professional Tools®

103 Bauer Drive, Oakland, NJ 07436 • 800-648-7229 • Fax: 800-286-0114 www.alpha-tools.com

Copyright © 2020 Alpha Professional Tools. All rights reserved.